


**Port Washington Water Pollution Control District  
Rehabilitated Sanitary Sewer Main Utilizing  
Cured-In-Place Pipe (CIPP) Liner Example Photo's**  
(Examples from Beachway Sanitary Sewer Mains Pre and Post CCTV Inspection Video)

**Mineral Deposits/ Infiltration:**

BEFORE:



AFTER:



**Broken Pipe (Crown):**

BEFORE:



AFTER:



**Broken Pipe/Open Joint/ Circular Crack with Groundwater Infiltration:**

BEFORE:





AFTER:



# Roots Intrusion at Pipe Joints:

BEFORE:



AFTER:



**Infiltration of Ground Water at Joint:**

BEFORE:



AFTER:

